



Texsolv Repair Heddle

This tip came from Erika de Ruiter sent to the WeaveTech discussion group:
(www.weavetech.org)

1. Take two Texsolv heddles.
2. Loop one end of each together in a sort of lark's head knot.
3. Place the looped end at the bottom of the shaft sticks.
3. Bring the heddles up, one on each side of the lower and upper shaft sticks.
4. Take a thrum of yarn and tie the heddles together at the top through the top loops.
5. The heddle eyes should be at the same height.
6. Thread the errant warp through both eyes.

And that is it!
If only I didn't ever need them . . .

